


DWG NO.
C-200030




THIS INFORMATION IS CONFIDENTIAL AND IS DISCLOSED TO YOU ON CONDITION THAT NO FURTHER DISCLOSURE IS MADE BY YOU TO OTHER THAN TOP-LINK PERSONNEL WITHOUT WRITTEN AUTHORIZATION FROM TOP-LINK LTD.

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK






USED ON

LDC
DIST





PAD OF PCB.

POINT OF MEASUREMENT




PICK&PLACE AREA

TOP-LINK



USED ON

LDC
DIST



PAD OF PCB.

POINT OF MEASUREMENT

